


1&2 bedroom apartments




2 bedroom apartment

Plot 284 – as shown







This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.




Second floor



First floor




Ground floor




Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


2 bedroom apartment

Plot 285 – as shown







This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.




Second floor



First floor



Ground floor




Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


2 bedroom apartment

Plot 286 – as shown







This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.




Second floor



First floor




Ground floor




Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


2 bedroom apartment

Plot 287 – as shown







This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.




Second floor



First floor



Ground floor




Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


2 bedroom apartment

Plots 288 & 291 - as shown







This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.




Second floor



First floor



Ground floor




Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


2 bedroom apartment

Plot 289 – as shown







This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.




Second floor



First floor



Ground floor




Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


2 bedroom apartment

Plot 290 – as shown







This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.




Second floor



First floor



Ground floor




Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.


1 bedroom apartment

Plot 292 – as shown







This is a Predicted Energy Assessment for properties that are incomplete. Once the property is completed, this rating will be updated and an official Energy Performance Certificate will be created for the property.




Second floor



First floor



Ground floor



Please ask your Sales Consultant for further details. St: Store cupboard. W: Wardrobe.